

FIG. 1




FIG. 2




FIG. 3

$$\begin{array}{l}
 \begin{array}{cccccc}
 C_1 & C_2 & \dots & C_k & \dots & C_n
 \end{array} \\
 \begin{array}{l}
 R_1 \\
 R_2 \\
 \vdots \\
 R_j \\
 \vdots \\
 R_m
 \end{array}
 \left[\begin{array}{cccccc}
 h_{11} & h_{12} & \dots & h_{1k} & \dots & h_{1n} \\
 h_{21} & h_{22} & \dots & h_{2k} & \dots & h_{2n} \\
 \vdots & \vdots & & \vdots & & \vdots \\
 h_{j1} & \dots & \dots & h_{jk} & \dots & h_{jn} \\
 \vdots & \vdots & & \vdots & & \vdots \\
 h_{m1} & \dots & \dots & h_{mk} & \dots & h_{mn}
 \end{array} \right]
 \begin{array}{l}
 x_1 \\
 x_2 \\
 x_3 \\
 \vdots \\
 x_n
 \end{array}
 \begin{array}{l}
 = \\
 z_1 \\
 z_2 \\
 z_3 \\
 \vdots \\
 z_m
 \end{array}
 \end{array}$$

FIG. 4

$$\begin{array}{l}
 \begin{array}{ccccccccc}
 C_1 & C_2 & \dots & C_{10} & \dots & C_{20} \\
 \hline
 R_1 & 1 & 0 & 0 & \dots & 0 \\
 R_2 & 0 & 1 & 0 & \dots & 0 \\
 \vdots & \vdots & \vdots & \vdots & \vdots & \vdots \\
 \vdots & \vdots & \vdots & \vdots & \vdots & \vdots \\
 R_{10} & 0 & 0 & 1 & \dots & 0
 \end{array} \\
 \begin{array}{c}
 \text{401} \\
 \text{402} \\
 \text{403}
 \end{array}
 \end{array}
 = \begin{array}{l}
 \begin{array}{c}
 x_1 \\
 x_2 \\
 \vdots \\
 \vdots \\
 x_{10} \\
 \vdots \\
 \vdots \\
 \vdots \\
 x_{20}
 \end{array} \\
 \begin{array}{c}
 0 \\
 0 \\
 1 \\
 0 \\
 0 \\
 0 \\
 1 \\
 0 \\
 0 \\
 1
 \end{array}
 \end{array}
 \begin{array}{l}
 \text{411} \\
 \text{412} \\
 \text{413}
 \end{array}$$

FIG. 5

